V-Range Software Release Notes



V-Range Software Pack - Revision W

V-Range_SwPack_W.zip (7029152)

V-Range Software Pack W		
Release Date:	15.06.2018	
Engineer:	Gary Moore & Jon Booty	

Hardware & Software Summary			
Device	Previous Version (V)	New Version (W)	
Software PLC:	22.00	23.00	
Software HMI:	22.00	23.00	
JetSym	5.2.1.3721	5.2.1.3721	
JetViewSoft	4.0.6.3489	4.0.6.3489	
JVM BL	1.11.0.00	1.11.0.00	
JVM 407 OS	1.20.1.00	1.20.1.00	
JVM 407B OS	4.01.0.63	4.03.0.16	
IO Node OS	3.32.0.01	3.32.0.01	
High Current Node OS	1.13.0.00	1.13.0.00	
Keypad Node OS	1.16.0.00	1.16.0.00	



V-Range Software Release Notes

JVM PLC & HMI Release Notes

Ensure JVM has shut down correctly before updating with new release

Updates:

VT/VS/VM

Added battery Isolator warning advice after switching off chassis ignition, to advise not to
isolate the battery system until after the audible confirmation and the warning on the
JVM has cleared. For JCB electronic engines, the warning will show for an increased time
as follows,

55kW/93kW S3B – 20 seconds 93kW T4 – 80 seconds

- Mute audible warning user preference page 4.16.1 clarified
- BEAM Airport sweep gear control added as a variable to the Beam option
- JVM 407B OS updated to 4.03.0.16 with improved camera visuals
- Service Indicator algorithm updated

VT

- Adblue Quality now displayed on 4.8.2. Dashes shown if Quality percentage is not available from DCU
- Engine CAN diagnostic updated and Adblue CAN diagnostic added to 4.2 CANbus information for JCB93kW T4 engines. Note: No icons will be shown when the sweeper ignition is switched off as ECUs are not powered

VS

- Volvo Automatic chassis option added
- The motor jog current, to help Hydrostatic engagement on the output side, will now be ignored by brake pedal logic. This is to improve the engagement process on chassis with automatic gearboxes
- Default values for hydrostatic drive improved to suit a wider range of chassis

Bug Fixes:

No bug fixes

